



FIRE ALARM INSPECTION REPORT INSP# 1036 6-2024

SITE BRENTON RESIDENCE 417 VALERIE CT INCLINE VILLAGE , NV 89451 INSPECTION DATE 6/27/2024	TESTING AGENCY BATTLEBORN ALARM 59 DAMONTE RANCH PKWY SUITE B541 RENO, NV 89521 PHONE # NV FIRE LIC CONTRACTORS LIC 775-796-1911 F-589 NV0089008	CENTRAL MONITORING STATION ALL AMERICAN MONITORING 1301 Sarasota Center Blvd Sarasota, FL 34240 PHONE # LICENSE (800) 318-9486 142301-002
--	---	--

PANEL OPERATION

CONTROL UNIT PASS	SUPERVISION PASS	REMOTE POWER PANELS PASS
LAMPS PASS	TROUBLE SIGNALS PASS	LOCAL ANNUNCIATORS PASS
TEST FUSES PASS	DISCONNECT SWITCHES PASS	REMOTE ANNUNCIATORS PASS
GROUND FAULT PASS		

CENTRAL STATION SIGNALS

ALARM PASS	RESTORE PASS	SUPERVISORY PASS	RESTORE PASS	TROUBLE PASS	RESTORE PASS
-------------------	---------------------	-------------------------	---------------------	---------------------	---------------------

INITIATING

ZONE	DEVICE TYPE	LOCATION	STATUS
01	WATERFLOW	WATERFLOW LOWER LEVEL MECHANICAL	PASS
02	SMOKE DETECTOR	FACP SMOKE DETECTOR	PASS
03	SMOKE DETECTOR	LOWER LEVEL IN FRONT OF ELEVATOR	PASS
04	SMOKE DETECTOR	1ST FLOOR IN FRONT OF ELEVATOR	PASS
05	SMOKE DETECTOR	2ND FLOOR IN FRONT OF ELEVATOR	PASS
06	SMOKE DETECTOR	TOP OF ELEVATOR SHAFT	PASS
09	SMOKE DETECTOR	LOWER LEVEL BED 2	PASS
09	SMOKE DETECTOR	LOWER LEVEL BED 1	PASS
09	SMOKE DETECTOR	LOWER LEVEL INFRONT OF BEDS 1 AND 2	PASS
09	SMOKE DETECTOR	LOWER LEVEL REC ROOM	PASS





FIRE ALARM INSPECTION REPORT INSP# 1036 6-2024

09	SMOKE DETECTOR	BOTTOM OF STAIRS	PASS
10	CO DETECTOR	LOWER LEVEL BED 2	PASS
10	CO DETECTOR	LOWER LEVEL BED 1	PASS
10	CO DETECTOR	LOWER LEVEL INFRONT OF BEDS 1 AND 2	PASS
10	CO DETECTOR	LOWER LEVEL REC ROOM	PASS
10	CO DETECTOR	BOTTOM OF STAIRS	PASS
11	SMOKE DETECTOR	1ST FLOOR MASTER BEDROOM	PASS
11	SMOKE DETECTOR	1ST FLOOR TOP OF STAIRS	PASS
11	SMOKE DETECTOR	1ST FLOOR OUTSIDE OF OFFICE	PASS
11	SMOKE DETECTOR	1ST FLOOR INSIDE OFFICE	PASS
11	SMOKE DETECTOR	1ST FLOOR GUEST BEDROOM	PASS
11	SMOKE DETECTOR	1ST FLOOR OUTSIDE OF GUEST BEDROOM	PASS
12	CO DETECTOR	1ST FLOOR MASTER BEDROOM	PASS
12	CO DETECTOR	1ST FLOOR TOP OF STAIRS	PASS
12	CO DETECTOR	1ST FLOOR OUTSIDE OF OFFICE	PASS





FIRE ALARM INSPECTION REPORT INSP# 1036 6-2024

12	CO DETECTOR	1ST FLOOR INSIDE OFFICE	PASS
12	CO DETECTOR	1ST FLOOR GUEST BEDROOM	PASS
12	CO DETECTOR	1ST FLOOR OUTSIDE OF GUEST BEDROOM	PASS
13	SMOKE DETECTOR	2ND FLOOR BUNK ROOM 1	PASS
13	SMOKE DETECTOR	2ND FLOOR BUNK ROOM 2	PASS
13	SMOKE DETECTOR	2ND FLOOR OUTSIDE OF BUNK ROOMS	PASS
13	SMOKE DETECTOR	2ND FLOOR BEDROOM 4	PASS
13	SMOKE DETECTOR	2ND FLOOR OUTSIDE BEDROOM 4	PASS
14	CO DETECTOR	2ND FLOOR BUNK ROOM 1	PASS
14	CO DETECTOR	2ND FLOOR BUNK ROOM 2	PASS
14	CO DETECTOR	2ND FLOOR OUTSIDE OF BUNK ROOMS	PASS
14	CO DETECTOR	2ND FLOOR BEDROOM 4	PASS
14	CO DETECTOR	2ND FLOOR OUTSIDE BEDROOM 4	PASS
			N/A





FIRE ALARM INSPECTION REPORT INSP# 1036 6-2024


NOTIFICATION

ZONE	DEVICE TYPE	LOCATION	STATUS
	Wireless siren	2nd floor	PASS

XBATTERY

ZONE	DEVICE TYPE	LOCATION	STATUS
	12v7ah	Panel	PASS
	12v7ah	Panel	PASS
	12v7ah	power supply	PASS

THIS TESTING WAS PERFORMED IN ACCORDANCE WITH APPLICABLE STANDARDS

INSPECTOR NAME	INSPECTOR NUMBER		DATE SIGNED
Shawn Fitzgerald	C8097		6/27/2024
CONTACT NAME	CONTACT TITLE		

